

布基胶带生成流程图

Flow Chart of Cloth Tape Production

第1步织布机织布
染色

Step 1 First Step: Weaving by Loom
Remove Stain Color



第2步 织布后检验存放

Step 2: Inspection and Storage after Weaving



第3步 进缸水洗去污

Step 3: Cylinder Washing to



第4步定型烘干

Step 4: Shaping and Drying
Inspection



第5步胶带基布检验

Step 5: Inspection of Tape Base Cloth



第6步切边检验

Step 6: Trimming and
Inspection



第7步 布基检验分流
布上胶贴合

Step 7: Inspection and Diversion of
Cloth Base



完成后进行电镀生产

第8步

导电布电镀生产

Step 8: Electroplating Production of
Conductive Cloth




完成后进行涂布上胶贴合

第9步


涂

Step 9: Coating, Gluing and
Laminating



第10步 导电布其它基布贴合后段
大母卷


Step 10: Subsequent Stage of
Laminating Conductive Cloth with
Other Base Cloths




导电布

第11步 导电布其它基布贴合冷却后收成

Step 11: After Laminating Conductive
Cloth with Other Base Cloths and
Cooling, Wind into a Large Mother
Roll



其它布



第12步 导电布其它基布胶带成品熟化 验

Step 12: Maturation of the Finished
Conductive Cloth and Other Base
Cloth Tapes



第13步 导电布其它基布熟化后剥纸

Step 13: Paper - Stripping Inspection
after the Maturation of Conductive
Cloth and Other Base Cloths



第14步 导电布其它基布检验后进行裁切

Step 14: Cutting Conductive Cloth and Other Base Cloths After Inspection



导电布



其它布

第15步 导电布其它基布 外观品检、加垫圈、包装

Step 15: Visual Inspection, Adding Washers, and Packaging of Conductive Cloth and Other Base Cloths



导电布



其它布

第16步

导电布其它基布 出货

Step 16: Shipment of Conductive Cloth and Other Base Cloths



导电布



其它布